
DSM I Series

Digital Force Gauges

User Manual



Locosc Ningbo Precision Technology Co., Ltd.


TABLE OF CONTENTS

Summary -----	4
Features -----	4
Specifications-----	4
Interface name and function-----	5
Button description -----	6
Operating parameter setting -----	6
Parameter setting -----	6
Threshold setting -----	7
Valid peak & drop -----	7
The peak hold time -----	7
Automatic shutdown -----	8
Acceleration of gravity -----	8
Communication RS232 settings -----	8
Language settings -----	9
The display settings -----	9

DSM Series specification parameter

Type	DSM-2	DSM-5	DSM-10	DSM-20	DSM-50	DSM-100	DSM-200	DSM-500
Load F.S	2N	5N	10N	20N	50N	100N	200N	500N
Indexing	0.001N	0.001	0.005	0.01N	0.01N	0.05N	0.1N	0.1N
Non-linearity					±0.2%			
Unit					N, kgf, lbf			
ADC Rate				1000Hz				
Power			Lithium battery	3.7V/3000mAh				
Sensor					Inside			
Work Temperature					0°C~40°C			
Store Temperature					-20°C~70°C			
Relative humidity					15%~80%			
Working environment					No vibration and corrosive medium			

DSM Series of contour structure size chart



Safety precautions

- ▲ Please read this manual carefully before using.
- ▲ In destructive testing, should do the protective work.
- ▲ To check fixture before the test fixture, do not use damaged or bending deformation.
- ▲ The maximum load sensor for the range 150%. 110% normal use is not recommended more than range.

Suggested use

- ▲ This instrument can only be used to test the pushing or pulling force, don't let the test rod bending or rotation direction force.
- ▲ Range of reasonable selection of push pull, the general should choose range than the shock load of at least one time.
- ▲ This instrument is not waterproof.
- ▲ Please use the matching charger adapter.

Summary

DSM series digital force gauge is a universal portable push and pull load testing instruments, has the advantages of small volume, light weight, easy to carry, multi-function, high precision characteristics, is suitable for sliding load testing of various products, insertion force test, destruction test, a small experimental machine and can be combined with all kinds of machine and fixture composition for different purposes.


1.1 Feature

- High resolution and high precision, high sampling rate up to 960Hz;
- free to set upper and lower deviation data, automatically determine whether or not qualified;
- Display flip function: test direction can be 180 degrees turn display;
- Full color display: TFT2.4 ', 320*240262K color lcd;
- 50 groups of test data, and automatically calculates the average storage data value, maximum value, minimum value;
- Three unit N, kgf, lbf automatic conversion;
- Peak hold automatic unlocking function (0~99 seconds set free);
- No operation automatic shutdown (0~99 minutes set free);
- With 7 measurement modes;
- Support for multiple languages;
- The serial output, which can be connected to the computer for analysis the printing process.
- Can set the gravity acceleration value;
- Have the pull pressure bar, and to change the colors of the progress bar and the voice prompt overload tensile stress;
- With the layer menu operation interface original
- Automatic monitoring of battery, battery instrument will automatically shut down.


1.2 Specifications

See page first specifications table

1.3 Interface name and function




1.4 Button description



2. Operating parameter setting

Press the [menu] button to enter setup menu



The settings menu consists of four items.

Press the [enter] button to enter parameter setting

Parameter Settings	Parameter Settings
1. Threshold	3. Peak Hold Time
2. Valid_Peak&Drop	4. Auto ShutDown
3. Peak Hold Time	5. Acceleration(g)
4. Auto ShutDown	6. Communication
Back	Back

2.1.1 Threshold setting

comparison of upper and lower limit setting




Press [Enter] to Save
Press [Back] to Cancel

2.1.2 Valid peak & drop

Peak(Effective peak): refers to the effective value of the minimum peak locking.

Drop: refers to the maximum effective, if the force values decreased to the peak of the x%, that is the fault of effective. The only effective in fracture mode.




Press [Enter] to Save
Press [Back] to Cancel

2.1.3 The peak hold time (range:[0 - 99]s)




Press [Enter] to Save
Press [Back] to Cancel

2.1.4 Auto shutdown (range :0-99 minute)




Press [Enter] to Save
Press [Back] to Cancel

2.1.5 Acceleration (range :9.7000~9.8999)




Press [Enter] to Save
Press [Back] to Cancel

2.1.6 communication RS232 settings




Press [Enter] to Save
Press [Back] to Cancel

2.2 language settings



Press [Enter] to Save
Press [Back] to Cancel

2.3 display settings



Press [Enter] to Save
Press [Back] to Cancel

2.4 , instrument calibration settings.

